

ReadmeWinNT_ver2.04.txt

=====
Attached file for updating: "s201_204.exe"
=====

This program will update the firmware of the DVD-R7211 to Version 2.04.
Please exit all applications prior to running this application.

At the Windows NT 4.0 server or workstation, confirm that the "auto insert notification" function is turned OFF:

1. Click "START", "RUN".
2. Type "REGEDIT" and hit the Enter key.
3. Follow this path:
HKEY_LOCAL_MACHINE/SYSTEM/Current Control Set/Service/Cdrom/Autorun
1: ON
0: OFF
default is "1" - Adjust setting to "0"
4. Exit

The next steps need to be performed at the DRM-7000. The correct screen displays are noted in parentheses following each step.

* * Please note the bay(s) and ID(s) your DVD-R7211 drive(s) use before continuing * *
(Example: Bay # 2 or 3 or 4 etc.)

5. Confirm that the FlexLibrary is ON and the robotics are ready
(Robotics Ready)
6. Unlock the key and push [FUNCTION]
(<Inquiry>)
7. Press and hold the [FUNCTION] and [LEFT ARROW KEY] buttons for 4 seconds
(Entering Test Mode!! OK?)
8. Press [ENT]
(select the mode. Diag, Demo, Info)
9. Press [LEFT] or [RIGHT] ARROW KEYS to move and select Diag then push [ENT]
(Robotics, Drive, or Sensor?)
- 10 Press [LEFT] or [RIGHT] ARROW KEYS to move and select Drive then push [ENT]
(Hot Line Check Drive # 1 start?)
11. Press [LEFT] or [RIGHT] ARROW KEYS to select the DVD-R7211's bay number
(Hot Line Check Drive# Start?)
12. Press [ENT] 5 times
(Hot Line Check Drive# END)

Return to the computer:

13. Double click on the "S201_204.exe" file to launch the firmware update program.
14. Follow the on-screen prompts to update the firmware.
If you receive the message, "The DVR-S201 is not found" , reboot your computer and confirm that the DVD-R7211 is recognized by your operating system.

Your DVD-R7211 drive firmware is now updated.

16. Follow steps 1 through 4 to turn your "auto insert notification" back ON.