



Firmware Update (version 1.08) for Pioneer In-Dash Navigation AV Receivers

August 10, 2018

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 1.08) for certain Pioneer In-Dash Navigation AV Receivers. **This firmware update is only for the following Pioneer In-Dash Navigation AV Receivers sold in the United States and Canada: AVIC-8201NEX, AVIC-7201NEX, AVIC-6201NEX, AVIC-8200NEX, AVIC-7200NEX, AVIC-6200NEX, and AVIC-5200NEX.**

Warning: Installation on any other product could cause irreversible damage.

This firmware update (version 1.08):

- Stabilizes Apple CarPlay connectivity
- Fixes an issue where no sound comes out when an iPhone is disconnected then reconnected via USB while using CarPlay
- In very rare cases, Navigation does not launch.

In order to perform this update, the following items are needed:

- Pioneer AVIC-8201NEX, AVIC-7201NEX, AVIC-6201NEX, AVIC-8200NEX, AVIC-7200NEX, AVIC-6200NEX, or AVIC-5200NEX In-Dash Navigation AV Receiver
- Blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Instructions on installing the firmware are provided on the same page as the firmware update. Installation of the update should take no more than ten minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website: pioneerelectronics.com/firmware
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash Navigation AV Receiver.

Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through parts.pioneerelectronics.com/contact.

Sincerely,

Pioneer Electronics (USA) Inc.