



Firmware Update (version 8.06) for Certain Pioneer In-Dash Digital Multimedia Video Receiver

March 7th, 2019

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 8.06) for certain Pioneer In-Dash Digital Multimedia Video Receiver. **This firmware update is only for the Pioneer In-Dash Digital Multimedia Video Receiver sold in the United States and Canada: MVH-2400NEX.**

Warning: Installation on any other product could cause irreversible damage.

This firmware update (version 8.06) fixes the following issues:

- Unit powers off when certain Android devices connected via Bluetooth
- Google Pixel 3 smartphones not recognized in Android Auto
- Minor bugs

In order to perform this update, the following items are needed:

- Pioneer MVH-2400NEX In-Dash Digital Multimedia Video Receiver
- Blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Instructions on installing the firmware are provided on the same page as the firmware update. Installation of the update should take no more than ten minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:
pioneerelectronics.com/firmware
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash Digital Multimedia Video Receiver.

Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through parts.pioneerelectronics.com/contact.

Sincerely,

Pioneer Electronics (USA) Inc.