



Firmware Update for Certain Pioneer Audio Receivers

Jan 12, 2022

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update for only the following Pioneer In-Dash AV Receivers. **This firmware update is only for the following Pioneer receivers sold in the United States and Canada:**

DMH-W4600NEX	DMH-W4660NEX	DMH-WC5700NEX	DMH-WC6600NEX
DMH-WT7600NEX	DMH-WT76NEX	DMH-WT8600NEX	

Warning: Installation on any other product could cause irreversible damage.

The update version to download and install will depend on the existing firmware version on your unit. **Please download the firmware update file according to your unit's current version.** (Refer to the Firmware Update Instructions for directions on checking the current version.)

Your unit's current firmware version	Update version
Version 2.00 or lower	Version 2.01

This firmware update provides usability enhancements and audio quality fixes.

In order to perform this update, the following items are needed:

- Pioneer receiver: DMH-W4600NEX, DMH-W4660NEX, DMH-WC5700NEX, DMH-WC6600NEX, DMH-WT7600NEX, DMH-WT76NEX, DMH-WT8600NEX
- Blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Instructions on installing the firmware are provided on the same page as the firmware update.

Installation of the update should take approximately 15 minutes to complete.

How to obtain the free firmware update:

1. Download the firmware update file to a computer from the Pioneer website: pioneerelectronics.com/firmware
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash AV Receiver.

Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through parts.pioneerelectronics.com/contact.

Sincerely,

Pioneer Electronics (USA) Inc.