



## Firmware Update (version 1.03) for AVIC-5100NEX, AVIC-6100NEX, and AVIC-7100NEX Receivers

March 23, 2015

**Dear Valued Pioneer Customer:**

We would like to inform you of the availability of a firmware update (version 1.03) for Pioneer AVIC-5100NEX, AVIC-6100NEX, and AVIC-7100NEX in-dash receivers. **This firmware update should be applied only to AVIC-5100NEX, AVIC-6100NEX, and AVIC-7100NEX receivers sold in the United States and Canada.** Installation on any other product could cause irreversible damage.

This firmware update (version 1.03) contains the following improvements:

- **Expanded compatibility with Google Android Auto™**
- **Fixed a pop noise problem while playing a music file in SD (AVIC-7100NEX)**
- **Minor bug fixes**

In order to perform this update, the following items are needed:

- Pioneer **AVIC-5100NEX, AVIC-6100NEX, or AVIC-7100NEX** receiver
- One of the following storage devices with at least 2 GB of storage capacity formatted to FAT32
  - USB storage device
  - SD card (AVIC-7100NEX only)

Before installing the update, please refer to the firmware update instructions. Installation of the update should take no more than ten minutes to complete.

### **How to Obtain the Free Firmware Update:**

1. Download the firmware update files to a computer from the Pioneer website:  
[pioneerelectronics.com/firmware](http://pioneerelectronics.com/firmware)
2. Transfer the files to an SD memory card or USB storage device for insertion into the AVIC-5100NEX, AVIC-6100NEX, or AVIC-7100NEX

### **Questions**

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through [parts.pioneerelectronics.com/contact](http://parts.pioneerelectronics.com/contact).

Sincerely,

**Pioneer Electronics (USA) Inc.**