



Firmware Update (version 1.03) for AVIC-8100NEX Receivers

March 23, 2015

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 1.03) for Pioneer AVIC-8100NEX in-dash receivers. **This firmware update should be applied only to AVIC-8100NEX receivers sold in the United States and Canada.** Installation on any other product could cause irreversible damage.

This firmware update (version 1.03) contains the following improvements:

- **Expanded compatibility with Google Android Auto™**
- **Fixed a pop noise problem while playing a music file in SD**
- **Minor bug fixes**

In order to perform this update, the following items are needed:

- Pioneer **AVIC-8100NEX** receiver
- One of the following storage devices with at least 2 GB of storage capacity formatted to FAT32
 - USB storage device
 - SD card

Before installing the update, please refer to the firmware update instructions. Installation of the update should take no more than ten minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:
pioneerelectronics.com/firmware
2. Transfer the files to an SD memory card or USB storage device for insertion into the AVIC-8100NEX.

Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through parts.pioneerelectronics.com/contact.

Sincerely,

Pioneer Electronics (USA) Inc.