



## Firmware Update (version 8.36) for Pioneer Audio Receivers

December 06, 2016

### Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 8.36) for select Pioneer audio receivers. **This firmware update is only for the following Pioneer models: FH-X830BHS, DEH-X8800BHS, DEH-X7800BHS, FH-X730BS, FH-X731BT, DEH-X6800BS, MVH-X580BS, DEH-X6910BT, DEH-X6900BT, MVH-X690BS, and MVH-X691BS (sold in the United States and Canada).** Installation on any other product could cause irreversible damage.

This firmware update (version 8.36) contains the following improvements:

- Improved Bluetooth connectivity
- Improved MTP performance
- Improved playback from USB Source
- Minor bug fixes

### In order to perform this update, the following items are needed:

- Pioneer receiver: FH-X830BHS, DEH-X7800BHS, DEH-X8800BHS, FH-X730BS, FH-X731BT, DEH-X6800BS, MVH-X580BS, DEH-X6910BT, DEH-X6900BT, MVH-X690BS, or MVH-X691BS
- A blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware update may be found at the link below. Installation of the update should take no more than ten minutes to complete.

### How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:  
[pioneerelectronics.com/firmware](http://pioneerelectronics.com/firmware)
2. Transfer the files to the USB storage device for insertion into the Pioneer receiver.

### Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM – 4:00 PM (Pacific Time), excluding holidays, or online through [parts.pioneerelectronics.com/contact](http://parts.pioneerelectronics.com/contact).

Sincerely,

**Pioneer Electronics (USA) Inc.**