

AVIC X-Series Firmware Update Change History

Applicable models: AVIC-X910BT, AVIC-X710BT, AVIC-X9115BT, AVIC-X7115BT

Ver 3.020100

CHANGE HISTORY:

- Fixes the case that VR beep sound was not played back when VR button was pressed.
- Enhances reliability during firmware update process.
- Contains performance improvements under low system voltage conditions.

Ver 3.010100

CHANGE HISTORY:

- Fixes the case that "distance to destination" is incorrectly displayed in French Canadian kilometer mode.
- Improves the reliability of "Delete All User Data" feature
- Improves 2D map display performance in scales > 20,000ft.
- Fixes the case that city names on 2D map may not be displayed when large amounts of MSN Traffic data is present.
- Enhances reliability during firmware update process.
- Fixes the case where Track Log data is not retained in memory when unit is shut off.
- Improves reliability of iPod alphabetical search feature.