



Firmware Update for Pioneer AVH-X3600BHS and AVH-X5600BHS In-dash DVD Receivers Used With SXV200/SXV300 Tuners for SiriusXM®

July 13, 2015

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update **only for Pioneer AVH-X5600BHS and AVH-X3600BHS In-dash DVD Receivers sold in the United States and Canada that are used with a SXV200/SXV300 Tuner for SiriusXM. If you own one of these receivers but do not have the SXV200/SXV300 Tuner and do not plan on adding one, you do not need this update and no further action needs to be taken.**

This update addresses very rare occurrences where the screen of an AVH-X5600BHS or AVH-X3600BHS receiver to which an SXV200/SXV300 Tuner has been added may freeze. If you have added the tuner or plan on doing so, you should have the update installed.

Obtaining this Firmware Update

Please have your SiriusXM Radio ID available before you call (tune to Channel "0" on SiriusXM and write down the Radio ID #).

To arrange for your receiver to be updated free of charge, please contact Pioneer's Warranty and Service Department toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through parts.pioneerelectronics.com/contact.

Sincerely,

Pioneer Electronics (USA) Inc.