



## Firmware Update (version 8.18) for Pioneer In-dash DVD Receivers

July 22, 2016

### Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 8.18) for the current lineup of Pioneer In-dash DVD receivers. **This firmware update is only for the following Pioneer In-dash DVD Receiver models sold in the United States and Canada: AVH-X1800S, AVH-X2800BS, AVH-X3800BHS, AVH-X4800BS, AVH-X5800BHS, AVH-X6800DVD, and AVH-X7800BT.**

**Warning:** Installation on any other product could cause irreversible damage.

This firmware update (version 8.18) contains the following improvement:

- **Add “AppRadioOne Sound” settings to System Menu.**

### In order to perform this update, the following items are needed:

- Pioneer In-Dash DVD receiver: **AVH-X1800S, AVH-X2800BS, AVH-X3800BHS, AVH-X4800BS, AVH-X5800BHS, AVH-X6800DVD, or AVH-X7800BT**
- Blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware are attached. Installation of the update should take no more than ten minutes to complete.

### How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website: [pioneerelectronics.com/firmware](http://pioneerelectronics.com/firmware)
2. Transfer the files to the USB storage device for insertion into the Pioneer In-dash DVD Receiver.

### Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM – 4:00 PM (Pacific Time), [Please note that per Service's suggestion, we use Pacific time, and they close at 4:00 PST / 7:00 EST, not 8:00 EST] excluding holidays, or online through [parts.pioneerelectronics.com/contact](http://parts.pioneerelectronics.com/contact).

Sincerely,

**Pioneer Electronics (USA) Inc.**