



Firmware Update (version 1.03) for Pioneer AVH-4200NEX Receiver

July 22, 2016

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 1.03) for the Pioneer **AVH-4200NEX** receiver. **This firmware update is only for AVH-4200NEX units sold in the United States and Canada.**

Warning: Installation on any other product could cause irreversible damage.

This firmware update (version 1.03) contains the following improvements:

- Improve boot time for playback from Pandora source
- Fix Artwork and Metadata for Pandora source
- Minor bug fixes

In order to perform this update, the following items are needed:

- Pioneer AVH-4200NEX receiver
- Blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware are attached. Installation of the update should take no more than ten minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website: pioneerelectronics.com/firmware
2. Transfer the files to the USB storage device for insertion into the Pioneer in-dash DVD Receiver.

Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM – 4:00 PM (Pacific Time), excluding holidays, or online through parts.pioneerelectronics.com/contact.

Sincerely,

Pioneer Electronics (USA) Inc.