



Firmware Update (version 8.31) for Pioneer In-dash DVD Receivers

February 16, 2015

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 8.31) for the current lineup of Pioneer DVD in-dash receivers. **This firmware update is only for the following Pioneer DVD in-dash receiver models, AVH-X1700S, AVH-X2700BS, AVH-X3700BHS, AVH-X4700BS and AVH-X5700BHS, sold in the United States and Canada.** Installation on any other product could cause irreversible damage.

This firmware update (version 8.31) contains all updates from version 8.29, including the addition of AppRadio One™ and support for iDatalink® Maestro™, as well as the following improvements:

- USB video quality improvements
- Minor bug fixes

In order to perform this update, the following items are needed:

- Pioneer DVD receiver: **AVH-X1700S, AVH-X2700BS, AVH-X3700BHS, AVH-X4700BS or AVH-X5700BHS**
- A blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Installation of the update should take no more than ten minutes to complete.

How to Obtain the Free Firmware Update

1. Download the firmware update instructions and firmware update files to a computer from the Pioneer website: pioneerelectronics.com/firmware
2. Transfer the files to the USB storage device for insertion into the Pioneer DVD receiver.

Questions

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through parts.pioneerelectronics.com/contact.

Sincerely,

Pioneer Electronics (USA) Inc.