



AppRadio 3 (SPH-DA110, SPH-DA210) Firmware Update Version 08.05 (October 2013)

October 17, 2013

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a free firmware update (version 08.05) for the Pioneer AppRadio 3 SPH-DA110 and SPH-DA210 in-dash multimedia systems. This firmware update applies only to AppRadio 3 units sold in the United States and Canada. This update (version 08.05) contains the following improvements:


- Improved GPS communication when using compatible navigation apps with an iPhone 5
- Adds MirrorLink support for Sony Xperia devices

This notice explains how to obtain the free firmware update for the AppRadio 3. **If you do not own an iPhone 5 or a Sony Xperia device, there is no need to install this update.**

HOW TO OBTAIN THE FREE FIRMWARE UPDATE:

1. Download the firmware update files to a computer from the Pioneer website: <http://www.pioneerelectronics.com/PUSA/Support/Downloads>
2. Transfer the files to a USB flash drive for connection to the AppRadio 3 SPH-DA110 or SPH-DA210.

HOW TO DETERMINE IF THE FIRMWARE UPDATE HAS ALREADY BEEN INSTALLED:

1. From the AppRadio 3 Home screen, horizontally swipe among the icons at the bottom to access the second page of icons and select [Settings].
2. Tap the  icon to access the System Settings screen.
3. Scroll down through the System Settings options and select [Firmware Version Information].
4. If the Firmware Version shown is 08.05 or higher, the firmware update has already been applied and no further steps are required. If the Firmware Version is lower than 08.05, you can proceed with the firmware update.

Questions

If you have any questions, please contact the Pioneer Customer Service Center toll free at 1-800-421-1404. Pioneer service representatives are available Monday through Friday, 10:30 a.m. to 7:00 p.m. (Eastern Time), except on Holidays.

Sincerely,

Pioneer Electronics (USA) Inc.