



Notice regarding tethering connectivity with iPhone 12 and higher models for Pioneer In-dash AV Receivers

January 12, 2022

Dear Valued Pioneer Customer:

We would like to provide an update on making a tethering connection between iPhone 12 devices (or higher) and the following Pioneer In-Dash AV Receivers sold in the United States and Canada: DMH-W4600NEX, DMH-W4660NEX, DMH-WC5700NEX, DMH-WC6600NEX, DMH-WT7600NEX, DMH-WT76NEX, and DMH-WT8600NEX.

iPhone 12 and higher models have a new set-up button, "Maximize Compatibility," for the tethering feature. If this setting is OFF (the default setting), you may not be able to make a tethering connection with one of the above receivers. If tethering is not working, please change the setting to "ON."

If you have any questions about the operation of your iPhone, please contact Apple. For questions about your Pioneer product, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 7:30 AM - 11:30 AM and 12:30 PM - 4:00 PM (Pacific Time), excluding holidays, or online through parts.pioneerelectronics.com/contact.

Sincerely,

Pioneer Electronics (USA) Inc.